



**photo 1:** Facing west toward the location. There is predominately undesirable vegetation (Cheat grass) at the location.



**photo 2:** North side of the location facing south.





**photo 3:** There are two boards found on location.



**photo 4:** There are noxious weeds (Musk thistle) growing at the location.





**photo 5:** There are pvc pipes at the location, presumably groundwater monitoring for remediation project.



**photo 6:** Facing east toward the surrounding undisturbed area. There are more desirable species found outside of the disturbance area.