



**photo 1:** Facing east toward the access road which has not been reclaimed and the cattle guard remains.



**photo 2:** There are noxious weeds along the access road. (Scotch thistle)





**photo 3:** Facing east toward the location.



**photo 4:** There are numerous square pipe in the ground at the location which appears to be for groundwater monitoring.





**photo 5:** There is equipment that remains at the east side of the location.



**photo 6:** There is no lock out/tag out that has been applied to the pipe infrastructure.





**photo 7:** There is an unknown capped pipe at Lat/Long:39.99704,-104.69336.



**photo 8:** Sign indicates Kerr McGee Gathering line.





**photo 9:** Facing toward backside of equipment that remains at the location.



**photo 10:** Facing west at the location.