

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/14/2017

Submitted Date:

06/14/2017

Document Number:

670201503**FIELD INSPECTION FORM**

Loc ID 450650 Inspector Name: BURGER, CRAIG On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 99999Name of Operator: OLD OPERATORS - STATUS UNKNOWNAddress: SEE COMMENT LINE IN WELLCity: XXXXXXX State: XX Zip: _____**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Andrews, Dave		david.andrews@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
450647	WELL	TA	05/17/2017	GW	077-10381	DB Orphan 8	TA

General Comment:

Orphan well plugging project #PO PHAA 2017*12735. Contractor is RACS LLC.

Inspected FacilitiesFacility ID: 450647 Type: WELL API Number: 077-10381 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment:

On location 9:00 am. Tagged at 10'. Material visible in casing that looks like foamed cement. Material is hard.
Gas detected on four gas meter in casing. Placed 25 gallons of Halliburton WellLock resin. Well was taking the resin and observed gas bubbling through it.
Taped top of resin at 10:20 at a depth of 6'3" below top of casing.
Off location 10:30.

Corrective Action: **Plug and abandon.**

Date: 06/19/2017