

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/16/2017

Submitted Date:

06/14/2017

Document Number:

688000006**FIELD INSPECTION FORM**
 Loc ID 312283 Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 7810Name of Operator: BERENERGY CORPAddress: 1888 SHERMAN ST - SUITE 600City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Hall, Dan		david@energyop.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
110650	PIT	AC			-	MERINO	EI

General Comment:

Environmental inspection related to planned oil skim culvert (tinhorn), produced water pit, well and production facility closure.
The eForm 27 describing location closure is currently in process.

Inspected Facilities									
Facility ID:	110650	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	EI

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Skimming/SettlingLined: NOPit ID: 110650Lat: 40.455538Long: -103.456683Reference Point: Other: Length: Width: **Lining:**

Liner Type:

Liner Condition:

Comment: Oil skim culvert (tinhorn) and associated produced water pit.

Corrective Action

Submit eForm 27 for approval (eForm 27 is in process).Date: 05/25/2017c**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date: **Netting:**

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688000007	Location drawing	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4170763