

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/23/2017

Submitted Date:

06/08/2017

Document Number:

674901676

FIELD INSPECTION FORM

Loc ID 325128 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 26625
 Name of Operator: ELM RIDGE EXPLORATION COMPANY LLC
 Address: 12225 GREENVILLE AVE STE 950
 City: DALLAS State: TX Zip: 75243-

Findings:

- 8 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Archuleta, Amy		aarchuleta@elmridge.net	
Lindeman, Terry	505-632-8048 EXT 210	tlindeman@elmridge.net	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
115631	PIT		09/23/1999		-	MCELVAIN DAKOTA 1	
214072	WELL	PR	10/01/2012	GW	067-05373	MCELVAIN DKTA UNIT 1	EI

General Comment:

On May 23, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Elm Ridge McElvain Dakota #1. For the most recent field inspection report for this facility, please refer to document #685303002. West Environmental Supervisor Alex Fischer and Catamount representative Jacob Franchini were on location during this inspection.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near well head.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	El Paso carsonite pipeline marker.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Operator contact information posted on well head sign.		
Corrective Action:		Date:	_____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	PIT		
Comment:	Post and wire fencing surrounding bermed area.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Pipeline riser and valve		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 115631 Type: PIT API Number: - Status: Insp. Status:

Facility ID: 214072 Type: WELL API Number: 067-05373 Status: PR Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			
Berms	Pass	Compaction	Pass			
Ditches	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: _____ Lined: NO Pit ID: 115631 Lat: 37.092739 Long: -107.764015

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Contact COGCC EPS staff for directives per Rule 905.b.

Date: 06/19/2017c

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action

Date: _____

COGCC Comments

Comment	User	Date
<p>On May 23, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Elm Ridge McElvain Dakota #1. For the most recent field inspection report for this facility, please refer to document #685303002. COGCC West Environmental Supervisor Alex Fischer and Catamount representative Jacob Franchini were on location during this inspection.</p> <p>This site visit was in response to corrective action noted in previous inspection regarding pit/bermed area. COGCC staff directed Catamount representative to submit a Site Investigation and Remediation Workplan for pit closure.</p>	hughesj	06/08/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401303897	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4166087
674901677	Pit/bermed area.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4166077
674901678	Riser and valve.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4166078
674901679	Meter house and pipeline risers.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4166079