

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/08/2017

Submitted Date:

06/08/2017

Document Number:

675103671

FIELD INSPECTION FORM

Loc ID 324004 Inspector Name: GRANAHAN, KYLE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100185
Name of Operator: ENCANA OIL & GAS (USA) INC
Address: 370 17TH ST STE 1700
City: DENVER State: CO Zip: 80202-

Findings:

12 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
, Encana		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211466	WELL	PR	11/01/1997	GW	045-07226	DODGE 8-12 (L8E)	EG

General Comment:

[2017 Flowline NTO inspection 1000' buffer](#)

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Present/complete		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Present/complete		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Present/complete		
Corrective Action:			Date:

Emergency Contact Number:

Comment: 970-285-2615

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	SEPARATOR		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Equipment:

Type			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:	39.45980/-107.69729		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	#		

Comment:	NOT IN USE; 1-2" water/oil dump line from separator to tank battery.		Date:	
Corrective Action:			Date:	
Type:	Horizontal Heated Separator	# 1		
Comment:	39.45980/-107.69729		Date:	
Corrective Action:			Date:	
Type:	Flow Line	#		
Comment:	IN USE; 1-2" steel riser from well to separator. 1 – 2" steel riser from gas out separator to sales line. 1 – 2" water/oil dump line from separator to tank. 1-2" water/oil dump line from separator to tank battery.		Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		39.459930,-107.697490
Comment:					Date:
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				Date:
Corrective Action:				Date:

Venting:

Yes/No	NO	Date:
Comment:		
Corrective Action:		

Flaring:

Type		Date:
Comment:		
Corrective Action:		

Inspected Facilities			
Facility ID: <u>211466</u>		Type: <u>WELL</u>	API Number: <u>045-07226</u>
Status: <u>PR</u>		Insp. Status: <u>EG</u>	
Producing Well			
Comment: <u>PR - via plunger lift, no leaks/venting - bradenhead/well pressure remotely monitored.</u>			
Corrective Action:		Date:	
Flowline			
#1	Type: Well Site	of Lines	
<u>Flowline Description</u>			
Flowline Type: <u>Well Site</u>	Size:	Material:	
Variance:	Age:	Contents:	
<u>Integrity Summary</u>			
Failures:	Spills:	Repairs Made:	
Coatings:	H2S:	Cathodic Protection:	
<u>Pressure Testing</u>			
Witnessed:	Test Result:	Charted:	
<u>COGCC Rules(check all that apply)</u>			
<input type="checkbox"/> 1101. Installation and Reclamation <input checked="" type="checkbox"/> 1102. Operations, Maintenance, and Repair <input type="checkbox"/> 1103. Abandonment			
Comment: <u>IN USE; 1-2" steel riser from well to separator. 1 – 2" steel riser from gas out separator to sales line. 1 – 2" water/oil dump line from separator to tank. 1-2" water/oil dump line from separator to tank battery.</u>			
Corrective Action: <u>NOT IN USE; 1-2" water/oil dump line from separator to tank battery.</u>		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Gravel	Pass					
		Gravel	Pass			
		Compaction	Pass			

Comment: [No sediment flow evident](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401304436	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4166658
675103672	Flowline photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4166655