

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/07/2017

Submitted Date:

06/08/2017

Document Number:

679700473**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
ALLISON, RICK 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
450930	SPILL OR RELEASE	AC	06/02/2017		-	Howard BC A 34-2	EI

General Comment:

COGCC Environmental Inspection of Spill 450930 reported at the Howard Bc A 34-2 tank battery

Environmental**Spill/Remediation:**

Comment: It appears area within the tank battery containment has been excavated and backfilled. Operator is to document remediation on Form 19 Supplemental Report along with detailed root cause of the dumphine failure and corrective actions to prevent further releases.

Corrective
Action:

Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401303783	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4165968
679700474	Excavated area	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4165963
679700475	Excvaated area near produced water vessel	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4165964