

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/15/2017

Submitted Date:

06/15/2017

Document Number:

674005365**FIELD INSPECTION FORM**
 Loc ID 307064 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10312Name of Operator: PROSPECT ENERGY LLCAddress: 1036 COUNTRY CLUB ESTATES DRCity: CASTLE ROCK State: CO Zip: 80108**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Twele, Megan		mtwele@progressivepcs.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216722	WELL	PR	03/30/1994	OW	069-05135	SABIN (MUDDY UNIT) 1	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Chainlin		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Flow line connects to header at the Martinez Battery and header connects to the Krause Battery. The pressure test witness here concerns the flow line segment from the wellhead to the Martinez battery.				
Corrective Action:				Date:	

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

--	--	--	--

**Inspected Facilities**Facility ID: 216722 Type: WELL API Number: 069-05135 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Comment: Plumbed to surface.

Corrective Action:

Date:

**Flowline**

#1 Type: Well Site

of Lines

**Flowline Description**Flowline Type: Well Site

Size:

Material:

Variance:

Age:

Contents:

**Integrity Summary**

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

**Pressure Testing**Witnessed: YesTest Result: PassCharted: Yes**COGCC Rules(check all that apply)**☐ 1101. Installation and Reclamation☐ 1102. Operations, Maintenance, and Repair☐ 1103. Abandonment

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment

User

Date

Witness of flow line pressure testing.

carlilec

06/15/2017

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674005366	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4171968">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4171968</a>