

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/05/2017

Submitted Date:

06/09/2017

Document Number:

673404695**FIELD INSPECTION FORM**

Loc ID 313417 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num:

Operator Information:OGCC Operator Number: 10407Name of Operator: ANTLER ENERGY LLCAddress: PO BOX 104City: BAGGS State: WY Zip: 82321**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Evans, Clay		antlerenergy@yahoo.com	
Neidel, Kris		kris.neidel@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
300984	WELL	PR	11/13/2009	GW	081-07461	CHEROKEE RIDGE 14-34R	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 307-380-7616

Corrective Action:

Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	
Produced Water	Tank	<= 1 bbl	
Comment:	Leak occuring at loadout valve on northern tank. Puddles of produced water with visible sheen present in berm.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: 06/10/2017

In Containment: Yes

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Flow Line	#		
Comment:	2 unused 1" steel riser at observed at wellhead, 2 unused 1" steel risers observed at separator, 1 unused 2" steel riser observed on location not marked for abandonment or locked out tagged out. NTO Phase 1, Part 2: Any existing flowline or pipeline riser not in use must be clearly marked using fluorescent paint, have all operating valves removed and be capped (locked out/tagged out, bull plugged, or blind flange) until it can be cut-off below grade and sealed pursuant to Rule 1103 and the statewide Flowline NTO.		
Corrective Action:	Comply with Phase I-Part 2 of the May 2, 2107 Flowline NTO.		Date: 05/30/2017
Type: Gas Meter Run	# 1		
Comment:	40.99456, -108.62566		
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:	40.99456, -108.62566		

Corrective Action:		Date:	
Type: Dehydrator	# 1		
Comment:	40.99456, -108.62566		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:	40.99456, -108.62566		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	400 BBLs	STEEL AST		40.994500,-108.026030	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate			Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 300984 Type: WELL API Number: 081-07461 Status: PR Insp. Status: PR**Producing Well**Comment: Review of monthly operations records indicate operator is delinquent in submitting monthly operations reports.Corrective Action: Submit required Form 7(s) to COGCC.Date: 07/09/2017

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No apparent soil migration; erosion or soil movement.](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401305201	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167318
673404706	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167300