

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/25/2017

Submitted Date:

06/06/2017

Document Number:

674104068**FIELD INSPECTION FORM**Loc ID 320391 Inspector Name: Wolfe, Stephen On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10548Name of Operator: HRM RESOURCES II LLCAddress: 410 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Pape, Terry	970-768-5700	tpape@hrmres.com	
Prohaska, April	303-893-6621	aprohaska@hrmres.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203629	WELL	PR	12/26/1994	GW	001-09189	HSR LAWSON 8-3	EG

General Comment:[2017 Flowline NTO Inspection](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Flow Line	#		corrective date
Comment:	NOT IN USE: 1-2" riser at the separator, marked for abandonment.		
Corrective Action:		Date:	
Type: Flow Line	#		
Comment:	IN USE: Wellhead- 2-2" risers, 1 wellsite, 1 bradenhead to surface. PROCESS PIPING- 1-1", wellhead to separator. SEPARATOR- 3-2" risers.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 203629 Type: WELL API Number: 001-09189 Status: PR Insp. Status: EG

Flowline

#1	Type: Well Site	of Lines	
<u>Flowline Description</u>			
Flowline Type: <u>Well Site</u>		Size:	Material:
Variance:		Age:	Contents:
<u>Integrity Summary</u>			
Failures:		Spills:	Repairs Made:
Coatings:		H2S:	Cathodic Protection:
<u>Pressure Testing</u>			
Witnessed: <u>No</u>		Test Result: <u>Pass</u>	Charted: <u>No</u>
<u>COGCC Rules(check all that apply)</u>			
<input type="checkbox"/> 1101. Installation and Reclamation <input type="checkbox"/> 1102. Operations, Maintenance, and Repair <input type="checkbox"/> 1103. Abandonment			
Comment:		5/6/17 Flowline from wellhead to separator tested with wellhead fluids to 250 psi for 30 mins by ZD with HRM.	
Corrective Action:		Date:	
#2	Type: Process Piping	of Lines	
<u>Flowline Description</u>			
Flowline Type: <u>Process Piping</u>		Size:	Material:
Variance:		Age:	Contents:
<u>Integrity Summary</u>			
Failures:		Spills:	Repairs Made:
Coatings:		H2S:	Cathodic Protection:
<u>Pressure Testing</u>			
Witnessed:		Test Result:	Charted:
<u>COGCC Rules(check all that apply)</u>			
<input type="checkbox"/> 1101. Installation and Reclamation <input type="checkbox"/> 1102. Operations, Maintenance, and Repair <input type="checkbox"/> 1103. Abandonment			
Comment:		5/6/17 Tested 1" from wellhead to separator with wellhead fluids to 100 psi for 30 mins by ZD with HRM.	
Corrective Action:		Date:	
#3	Type: Sales Line	of Lines	
<u>Flowline Description</u>			
Flowline Type: <u>Sales Line</u>		Size:	Material:
Variance:		Age:	Contents:
<u>Integrity Summary</u>			
Failures:		Spills:	Repairs Made:
Coatings:		H2S:	Cathodic Protection:
<u>Pressure Testing</u>			
Witnessed: <u>No</u>		Test Result: <u>Pass</u>	Charted: <u>No</u>

Inspector Name: Wolfe, Stephen

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation

☐ 1102. Operations, Maintenance, and Repair

☐ 1103. Abandonment

Comment: 5/6/17 Sales line from separator to gas sales meter tested with wellhead fluids to 100 psi for 30 mins by ZD with HRM.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401305324	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167615
674104177	Wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167573
674104178	Separator	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167574
674104179	Pressure test report	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167575