

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/25/2017

Submitted Date:

06/06/2017

Document Number:

674104069**FIELD INSPECTION FORM**Loc ID 320423 Inspector Name: Wolfe, Stephen On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10548Name of Operator: HRM RESOURCES II LLCAddress: 410 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Pape, Terry	970-768-5700	tpape@hrmres.com	
Prohaska, April	303-893-6621	aprohaska@hrmres.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203724	WELL	PR	03/15/1995	OW	001-09284	HSR-VAN SCHAACK 2-11	EG

**General Comment:**[2017 Flowline NTO Inspection](#)

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Flow Line	#		corrective date
Comment:	NOT IN USE: SEPERATOR- 4-2" steel risers, marked for abandonment.		
Corrective Action:		Date:	
Type: Flow Line	#		
Comment:	IN USE: WELLHEAD- 2-2" steel risers, 1 wellsite and 1 surface casing, 1-1" wellhead to separtor, SEPARATOR- 5-2" steel risers. 2 wellsite, 2 bypass, 1 gas sales. PROCESS PIPING- 3-1" steel risers, 1 to each well and 1 to ECD, all connected. GAS SALES- 1-2" steel riser. Common battery for Van Schaak 2-11 and 8-11.		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

## Inspected Facilities

Facility ID: 203724 Type: WELL API Number: 001-09284 Status: PR Insp. Status: EG

## Flowline

#1	Type: Well Site	of Lines	
<u>Flowline Description</u>			
Flowline Type: <u>Well Site</u>		Size:	Material:
Variance:		Age:	Contents:
<u>Integrity Summary</u>			
Failures:		Spills:	Repairs Made:
Coatings:		H2S:	Cathodic Protection:
<u>Pressure Testing</u>			
Witnessed: <u>No</u>		Test Result: <u>Pass</u>	Charted: <u>No</u>
<u>COGCC Rules(check all that apply)</u>			
<input type="checkbox"/> 1101. Installation and Reclamation <input type="checkbox"/> 1102. Operations, Maintenance, and Repair <input type="checkbox"/> 1103. Abandonment			
Comment:		5/5/17 Flowline from wellhead to separator tested with wellhead fluids to 255 psi for 60 mins by ZD with HRM.	
Corrective Action:		Date:	
#2	Type: Process Piping	of Lines	
<u>Flowline Description</u>			
Flowline Type: <u>Process Piping</u>		Size:	Material:
Variance:		Age:	Contents:
<u>Integrity Summary</u>			
Failures:		Spills:	Repairs Made:
Coatings:		H2S:	Cathodic Protection:
<u>Pressure Testing</u>			
Witnessed:		Test Result:	Charted:
<u>COGCC Rules(check all that apply)</u>			
<input type="checkbox"/> 1101. Installation and Reclamation <input type="checkbox"/> 1102. Operations, Maintenance, and Repair <input type="checkbox"/> 1103. Abandonment			
Comment:		5/5/17 1" supply line from separator to wellhead tested with wellhead fluids to 100 psi for 15 mins by ZD with HRM.	
Corrective Action:		Date:	
#3	Type: Sales Line	of Lines	
<u>Flowline Description</u>			
Flowline Type: <u>Sales Line</u>		Size:	Material:
Variance:		Age:	Contents:
<u>Integrity Summary</u>			
Failures:		Spills:	Repairs Made:
Coatings:		H2S:	Cathodic Protection:
<u>Pressure Testing</u>			
Witnessed: <u>No</u>		Test Result: <u>Pass</u>	Charted: <u>No</u>

**COGCC Rules(check all that apply)**☐ 1101. Installation and Reclamation☐ 1102. Operations, Maintenance, and Repair☐ 1103. Abandonment**Comment:** 5/6/17 Sales line from separator to gas sales meter tested with wellhead fluids to 100 psi for 30 mins by ZD with HRM.**Corrective Action:****Date:****Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401305325	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167616">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167616</a>
674104180	Wellhead	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167576">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167576</a>
674104181	Separator	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167577">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167577</a>
674104182	ECD	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167578">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167578</a>
674104183	Separator	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167579">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167579</a>
674104184	Separator	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167580">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167580</a>
674104185	Separator	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167581">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167581</a>
674104253	Pressure test report	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167582">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167582</a>