

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/14/2017

Submitted Date:

06/16/2017

Document Number:

674603383**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
 \_\_\_\_\_ Maclaren, Joe \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 4680Name of Operator: DCP MIDSTREAM LPAddress: 370 17TH STREET - SUITE 2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
JONES, JEANETTE		jajones@dcpmidstream.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Hayes, Branden	970-373-8905	bshayes@dcpmidstream.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451003	SPILL OR RELEASE	AC	06/08/2017		-	Maggie 10"	EG

**General Comment:**

Engineering Integrity Inspection performed on June 14th, 2017 in response to initial form 19 spill report Doc #401303996 received by COGCC on 06/08/2017 that outlines: DCP Environmental was informed by DCP Pipeline group of a possible pipeline release on June 5th, 2017 around 10:00 am. At the time of notification the DCP pipeline group had identified that a 10 inch gathering line had developed a leak, but there was no visible staining on the surface to indicate soil contamination. The pipeline was shut-in and depressurized and will not return to operation until the leak has been repaired. The pipeline repair crew and excavation team are currently scheduled to repair the gathering line the week of June 12th, 2017. Details of observations made during this field inspection are available in the comment section of this report. Photo's uploaded and can be accessed via link(s) at the end of this report.

**Inspected Facilities**Facility ID: 451003 Type: SPILL OR API Number: - Status: AC Insp. Status: EG**COGCC Comments**

Comment	User	Date
<p>The area where the possible release occurred has been grubbed/ graded. It is unclear if pipeline repairs have already been completed. There were no DCP Midstream employees or contract personnel on site; no cleanup/ remediation or pipeline repair work taking place at the time of this field inspection.</p> <p>Note: Please document the findings of root cause of failure evaluation, measures taken to prevent the problem from reoccurring and description of pipeline repairs completed on the COGCC supplemental form 19.</p>	maclarej	06/16/2017

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674603385	Site of possible release - clean & grubbed	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4172523">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4172523</a>