

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/17/2017

Submitted Date:

06/15/2017

Document Number:

687900006**FIELD INSPECTION FORM**

Loc ID 322222 Inspector Name: DURAN, JOHN On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 16245Name of Operator: CHARLES ANTHONY FUNERAL HOMEAddress: 225 E MAINCity: FLORENCE State: CO Zip: 81226**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Harwood, Lloyd	719-458-1552/ 719-334-2445	harwoodfuneral@yahoo.com	Canyon City Office
Malin, Carol	719-458-1552	carol.harwoodfuneral@gmail.com	All Inspections
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210030	WELL	DM	05/12/1996	GW	043-06108	PRIDE OF WEST 1	DM

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	and seperator fenced by guard rail.		
Corrective Action:		Date:	

Equipment:

Type: Ancillary equipment	# 1		corrective date
Comment:	Wellhead		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	210030	Type:	WELL	API Number:	043-06108	Status:	DM	Insp. Status:	DM
Producing Well									
Comment:	PR - Domestic producer that heats funeral parlor and heats retort oven for crematorium.								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Paving	Pass	Paving	Pass			

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On site at 8:30 am. With borrowed ladder I proceeded with leak check on 3" line. The 3" line runs from the well to the crematorium and is 8 ft above grade. It runs 70 ft from the well to the retort oven. I check for leaks with soapy water along the entire 70 ft. I found no leaks for the 3" line and 1" line. I go into the basement of the funeral parlor and see that the 1" line goes into the boiler and hot water heater. Off site at 12:30 pm.	duranj	06/15/2017