

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/25/2017

Submitted Date:

06/14/2017

Document Number:

670201484**FIELD INSPECTION FORM**

Loc ID 322296 Inspector Name: BURGER, CRAIG On-Site Inspection ☐ 2A Doc Num:

Operator Information:OGCC Operator Number: 10043Name of Operator: MACKLEY* ARNOLD & DARLEENAddress: 4031 COUNTY RD 320City: RIFLE State: CO Zip: 81650**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------------|-------|-------------------------------|---------|
| Schlagenhauf, Mark | | mark.schlagenhauf@state.co.us | |
| Andrews, Dave | | david.andrews@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 210181 | WELL | DM | 02/24/1961 | GW | 045-05076 | ED T. BERNKLAU 1 | DM |

General Comment:

Domestic flowline inspection. Domestic well has subsequently been plugged and flowline was re-routed by the land owner.

Inspected FacilitiesFacility ID: 210181 Type: WELL API Number: 045-05076 Status: DM Insp. Status: DM**Flowline**

| #1 | Type:Non-Well Site | of Lines | |
|----|--------------------|----------|--|
|----|--------------------|----------|--|

Flowline Description

Flowline Type: Non-Well Site Size: Material: Carbon Steel
 Variance: No Age: 1-5 Yrs Contents: Natural Gas

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Domestic flowlines from a gathering line to two houses, the Giles house (owned by TEP) and the Mackley residence. Gas is odorized by a replaceable canister. TEP is gathering information on domestic taps and associated documentation regarding responsibility for maintenance and testing.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------|---|
| 670201506 | Flowline Alignment | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4172902 |