

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/02/2017

Submitted Date:

06/12/2017

Document Number:

666803218

### FIELD INSPECTION FORM

Loc ID 322296 Inspector Name: Murray, Richard On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10043  
 Name of Operator: MACKLEY\* ARNOLD & DARLEEN  
 Address: 4031 COUNTY RD 320  
 City: RIFLE State: CO Zip: 81650

**Findings:**

- 1 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Murray, Richard	970-623-9782	G.Richard.Murray@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210181	WELL	DM	02/24/1961	GW	045-05076	ED T. BERNKLAU 1	DM

**General Comment:**

**Inspected Facilities**

Facility ID: 210181 Type: WELL API Number: 045-05076 Status: DM Insp. Status: DM

**Workover**

Comment: June 2, 2017 Friday  
 Tbg on a vacuum. Casing static. POOH with tbg, RU RMWS to pull CBL Tagged fluid in well at 440' RIH and tagged with tools at 3952' Pulled CBL from tag to surface. RIH with tbg to 3627' Mixed and spotted 22 sks Class G cement with 50# of cacl2 added to slurry. POOH with 30 joints. Waited 2.5 hrs on Cement to set. RIH with tbg, tagged at 3353'. POOH with tbg. PU and RIH with a 4-1/2"

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401306406	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4168585">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4168585</a>