

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/31/2017

Submitted Date:

06/08/2017

Document Number:

670201495**FIELD INSPECTION FORM**

Loc ID 450650 Inspector Name: BURGER, CRAIG On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 99999Name of Operator: OLD OPERATORS - STATUS UNKNOWNAddress: SEE COMMENT LINE IN WELLCity: XXXXXXX State: XX Zip: \_\_\_\_\_**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☒ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Andrews, Dave		david.andrews@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
450647	WELL	TA	05/17/2017	GW	077-10381	DB Orphan 8	TA

**General Comment:**

Orphan well plugging project #PO PHAA 2017\*12735. Contractor is RACS LLC.

**Inspected Facilities**Facility ID: 450647 Type: WELL API Number: 077-10381 Status: TA Insp. Status: TA**Workover**

Comment: On location 7am. RACS setting up for circulation and picking up power swivel.  
10:30 picking up washover pipe to begin washing over fish. 11:55 began washing over.  
At 12' water began coming around cellar.  
Cleaned up. Lassoed fish with whipstock and pulled with 5000 lbs. No movement of fish.  
Began rigging up to cement. Dave Andrews on location 5-8pm.  
Mix and pump 30 sacks Class G down casing to heal around cellar (15.8 ppg) at 6pm.  
Wash out and shut down for night with casing shut in.  
Dave Andrews returned at 10:30pm and opened valve, some pressure and blew down in  
about 1 minute. No fluid.

Corrective Action: **Plug and abandon.**

Date: 06/09/2017

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401306469	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4168716">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4168716</a>