

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/24/2017

Submitted Date:

06/19/2017

Document Number:

674901729**FIELD INSPECTION FORM**
 Loc ID 415495 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 5Name of Operator: COLORADO OIL & GAS CONSERVATIONAddress: 1120 LINCOLN ST SUITE 801City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
415547	WELL	SI	03/22/2011	GW	067-09804	PALMER RANCH 1	EI

**General Comment:**

On May 24, 2017 COGCC SW EPS Jim Hughes and West Environmental Supervisor Alex Fischer conducted an environmental field inspection of the COGCC Palmer Ranch #1. For the most recent field inspection report for this facility, please refer to document #674901180.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign mounted to stock panel enclosure.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Posted on sign mounted to stock panel enclosure.

Corrective Action:  Date: Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Stock panel enclosure surrounds all equipment on site.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Telemetry.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	In-Situ data logger.		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	415547	Type:	WELL	API Number:	067-09804	Status:	SI	Insp. Status:	EI

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On May 24, 2017 COGCC SW EPS Jim Hughes and West Environmental Supervisor Alex Fischer conducted an environmental field inspection of the COGCC Palmer Ranch #1. For the most recent field inspection report for this facility, please refer to document #674901180. During this site visit, all eight of the desiccant bags were replaced. The Desi-tube installed on 6/24/16 was still functional and was left in place.	hughesj	06/19/2017

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901730	Palmer Ranch MW location photol	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4173899">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4173899</a>
674901731	Troll Link 201 equipment enclosure.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4173900">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4173900</a>