

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/24/2017

Submitted Date:

06/19/2017

Document Number:

674901736**FIELD INSPECTION FORM**
 Loc ID 334324 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 5Name of Operator: COLORADO OIL & GAS CONSERVATIONAddress: 1120 LINCOLN ST SUITE 801City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267696	WELL	AC	06/15/2015	OBW	067-08801	MONITOR WELL 35-7-8-1	EI
267858	WELL	AC	06/15/2015	OBW	067-08811	MONITOR WELL 35-7-8-2	EI

General Comment:

On May 24, 2017 COGCC SW EPS Jim Hughes and West Environmental Supervisor Alex Fischer conducted an environmental field inspection of the COGCC SFTC MW 35-7-8 #1 and #2. For the most recent field inspection report for this facility, please refer to document #674901177.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Signs mounted to protective steel cages surrounding well heads.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Sign mounted to skid mounted shack housing ancillary equipment.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	4' x 4' x 4' expanded metal and angle iron protective cages.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Telemetry.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	In-Situ data logger.		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	<u>267696</u>	Type:	<u>WELL</u>	API Number:	<u>067-08801</u>	Status:	<u>AC</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>267858</u>	Type:	<u>WELL</u>	API Number:	<u>067-08811</u>	Status:	<u>AC</u>	Insp. Status:	<u>EI</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On May 24, 2017 COGCC SW EPS Jim Hughes and West Environmental Supervisor Alex Fischer conducted an environmental field inspection of the COGCC SFTC MW 35-7-8 #1 and #2. For the most recent field inspection report for this facility, please refer to document #674901177. During this site visit, all of the desiccant packs and the desi-tube were replaced. This was last performed on 6/24/16.	hughesj	06/19/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901737	SFTC MW #2 well head and protective cage.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174137
674901739	Troll Link 201 equipment enclosure.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174138