

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/19/2017

Submitted Date:

06/19/2017

Document Number:

673404716**FIELD INSPECTION FORM**Loc ID 432878 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10454Name of Operator: PETROSHARE CORPORATIONAddress: 9635 MAROON CIRCLE #400City: ENGLEWOOD State: CO Zip: 80112**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Witsell, Fred	303-500-1168	fwitsell@petrosharecorp.com	
Powell, Harold		hpowell@petrosharecorp.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432876	WELL	PR	12/17/2014	OW	081-07778	Voloshin 3-25	WK

**General Comment:**

Inspector on location to witness MIT. Form 42 notice document number 401304183. MIT passed at 310 PSI for 15 minutes.

Inspected Facilities									
Facility ID:	432876	Type:	WELL	API Number:	081-07778	Status:	PR	Insp. Status:	WK
Workover									
Comment:	Inspector on location to witness MIT. Form 42 notice document number 401304183. MIT passed at 310 PSI for 15 minutes.								
Corrective Action:					Date:				

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<p>Comment: <a href="#">No apparent soil migration; erosion or soil movement.</a></p> <p>Corrective Action: <input type="text"/> Date: _____</p> <p><b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

**COGCC Comments**

Comment	User	Date
<a href="#">Inspector on location to witness MIT. Form 42 notice document number 401304183. MIT passed at 310 PSI for 15 minutes.</a> <a href="#">No follow-up inspection to inspection document number 673403598 was performed. Follow-up will be performed after workover leaves location.</a>	waldrone	06/19/2017