

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/16/2017

Submitted Date:

06/20/2017

Document Number:

673715633

**FIELD INSPECTION FORM**

Loc ID 320788 Inspector Name: Sherman, Susan On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10618  
Name of Operator: BISON OIL & GAS LLC  
Address: 999 18TH STREET #3370  
City: DENVER State: CO Zip: 80202

**Findings:**

- 6 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
O&G, Bison	720-644-6997	ops@bisonog.com	<a href="#">All inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204926	WELL	PR	11/27/2006	OW	005-07011	HSR-BENNETT 16-20	EG

**General Comment:**

[2017 Flowline NTO Inspection 1000' Buffer](#)  
[Weeds inside berms noted in previous inspection were sprayed.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

**Good Housekeeping:**

Type	OTHER		
Comment:	Black plastic behind crude oil tank (see attached photo).		
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 204926 Type: WELL API Number: 005-07011 Status: PR Insp. Status: EG

**Producing Well**

Comment: PR. Mar 2017 reported to COGCC database.

Corrective Action:

Date:

**Flowline**

#1 Type: Process Piping

of Lines

Flowline Description

Flowline Type: Process Piping

Size:

Material:

Variance:

Age:

Contents:

Integrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

Pressure Testing

Witnessed: No

Test Result:

Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation

1102. Operations, Maintenance, and Repair

1103. Abandonment

Comment: Abandoned flowlines that were removed are corroded (see attached photos). Verify integrity of remaining pipe through flowline testing.

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673715634	Bison HSR-Bennett 16-20 EI	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175671">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4175671</a>