

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/08/2017

Submitted Date:

06/14/2017

Document Number:

670201501**FIELD INSPECTION FORM**
 Loc ID 450650 Inspector Name: BURGER, CRAIG On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 99999Name of Operator: OLD OPERATORS - STATUS UNKNOWNAddress: SEE COMMENT LINE IN WELLCity: XXXXXXX State: XX Zip: **Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Andrews, Dave		david.andrews@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
450647	WELL	TA	05/17/2017	GW	077-10381	DB Orphan 8	TA

General Comment:Orphan well plugging project #PO PHAA 2017*12735. Contractor is RACS LLC.

Inspected FacilitiesFacility ID: 450647 Type: WELL API Number: 077-10381 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: On location 7am. Tagged top of cement at 36.82' with tubing. Rigged up cement and mixed and pumped 40 sacks of Class G at 15.8 ppg with hydrolizer and CaCl to stabilize backside of casing. Wait on cement. Halliburton placed 15 gallons of Wellock Resin, planned for 9 linear feet of wellbore. Off location 17:00.

Corrective Action: Plug and abandon.

Date: 06/19/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401308776	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4170650