

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER Estimated Spill Volume: _____

Comment: Follow up to F-19 pw spill #452872. Overflow from HDPE lined SPCC to tilled earth swale tertiary. No visible signs such as staining or odor from spill remain. De minimus rainwater in SPCC has no sheen or odor. Tilled soils in tertiary barrier between SPCC and Ryan Gulch have no staining or odor. Ryan Gulch shows no indications of having been impacted.

Corrective Action: Per F-19 COA: Assess nature and extent of contamination with confirmation soil samples. Remediate to Table 910-1 standards and provide documentation in a either a Supplemental F-19 if cleaned up immediately and/or F-27 if extended remediation such as landfarming contaminated soil is required. Landfarming must also be approved by surface owner. Documentation must include a figure showing spill area with sample locations plus laboratory results.

Date: 07/19/2017

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401308707	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4170538
674300900	SPCC looking NE	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4170536
674300901	SPCC and tertiary dirt swale north of tank battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4170537