

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/16/2017

Submitted Date:

06/14/2017

Document Number:

688000006

FIELD INSPECTION FORM

Loc ID 312283 Inspector Name: YOUNG, ROB On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 7810
Name of Operator: BERENERGY CORP
Address: 1888 SHERMAN ST - SUITE 600
City: DENVER State: CO Zip: 80203

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Hall, Dan		david@energyop.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
110650	PIT	AC			-	MERINO	EI

General Comment:

Environmental inspection related to planned oil skim culvert (tinhorn), produced water pit, well and production facility closure. The eForm 27 describing location closure is currently in process.

Inspected Facilities

Facility ID: 110650 Type: PIT API Number: - Status: AC Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Skimming/Settling Lined: NO Pit ID: 110650 Lat: 40.455538 Long: -103.456683

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: Oil skim culvert (tinhorn) and associated produced water pit.

Corrective Action: Submit eForm 27 for approval (eForm 27 is in process).

Date: 05/25/2017c

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action:

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action:

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action:

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401308950	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4170779
688000007	Location drawing	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4170763