



**photo 1:** Facing southeast along the former access road. The former road is still visible and there is predominately undesirable vegetation along the road.



**photo 2:** Facing southeast toward the location. There is no equipment that remains and the southern portion is cultivated.



**photo 3:** Facing southeast toward the former tank battery site near the location. Unused equipment is being stored in this area.



**photo 4:** Facing north towards unused equipment that remains at the former tank battery site.



**photo 5:** There is oily soil waste noticed where unused equipment is stored.



**photo 6:** Facing south toward the former tank battery site where unused equipment is being stored.



**photo 7:** There is a pipe riser that remains at the former tank battery site.  
Lat/Long:39.94706,-104.42354



**photo 8:** One end of the pipe riser has been disconnected, capped and locked out.  
Lat/Long:39.94706,-104.42354