

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401314253

Date Received:
06/21/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-3779

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Luke Reddy

970-515-1292

luke.reddy@anadarko.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 674603325

Inspection Date: 05/17/2017

FIR Submit Date: 05/19/2017

FIR Status: _____

Inspected Operator Information:

Company Name: KERR MCGEE OIL & GAS ONSHORE LP

Company Number: 47120

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-3779

LOCATION - Location ID: 432040

Location Name: RALPH Number: 13N-19HZ County: WELD

Qtrqr: NWN Sec: 19 Twp: 1N Range: 67W Meridian: 6
W

Latitude: 40.043190 Longitude: -104.938186

FACILITY - API Number: 05-123- -00 Facility ID: 432044

Facility Name: RALPH Number: 34C-19HZ

Qtrqr: NWN Sec: 19 Twp: 1N Range: 67W Meridian: 6
W

Latitude: 40.043190 Longitude: -104.938186

CORRECTIVE ACTIONS:

1 CA# 76887

Corrective Action:

Date: 06/19/2017

Email COGCC Engineering Integrity staff the following information:
1) Root cause of failure evaluation/ what caused a "weak" point and where was it located (was it a bad poly fusion at the carbon steel riser tie in?)
2) Measures taken to prevent the problem from re-occurring (are all 1" poly lines associated with wells on this location/ facility at risk?)
3) Description of the flowline repair completed (Describe how the 1" poly line was repaired)
4) A copy of the flowline pressure testing chart/ data verifying integrity of repairs completed
5) GPS data for the riser locations associated with this flowline
6) Provide timeframe for installation and use of air compressor (to be used on all 1" poly lines on this well pad?)
7) Describe what equipment the 1" poly flowline is servicing

Response: CA COMPLETED

Date of Completion: 06/19/2017

Operator Comment: The requested information was sent to COGCC Engineering via email.
See attached.

COGCC Decision:

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: The requested information was sent to COGCC Engineering via email.
See attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Luke Reddy

Signed:

Title: Regulatory Specialist

Date: 6/21/2017 10:35:12 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401314257	Ralph Response
-----------	----------------

Total Attach: 1 Files