

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/21/2017

Submitted Date:

06/22/2017

Document Number:

666803268**FIELD INSPECTION FORM**
 Loc ID 336022 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 1600 BROADWAY ST STE 2600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284504	WELL	PR	06/11/2013	GW	045-12189	HANGS B1	PR
284505	WELL	PR	06/11/2013	GW	045-12190	HANGS B3	PR

General Comment:[2017 Flowline NTO Inspection 1000' Buffer](#)

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Flow Line

#

Comment:

In use; 2-2" steel risers at wellhead, 8-2", 2-3", 1-1" risers at separators, 2-3", 1-1" risers at tanks, 1-1" gas feed to ECB

Corrective Action:

Date:

Type: Pig Station

1

Comment:

Corrective Action:

Date:

Type: Flow Line

#

Comment:

Not in use 4-2", 2-3", 1-1" Marked with paint, see photo

Corrective Action:

Date:

Type: Horizontal Heated Separator

4

Comment:

39.534252/-107.677947

Corrective Action:

Date:

Type: Plunger Lift

2

Comment:

39.534468/*-107.678240

Corrective Action:

Date:

Type: Emission Control Device

1

Comment:

39.534245/-107.678684

Corrective Action:

Date:

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 284504 Type: WELL API Number: 045-12189 Status: PR Insp. Status: PR**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID: 284505 Type: WELL API Number: 045-12190 Status: PR Insp. Status: PR**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	In Process					
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666803278	URSA NTO 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4177785
666803280	URSA NTO	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4177786
666803281	URSA NTO 3	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4177787
666803282	URSA NTO 4	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4177788