

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/22/2017

Submitted Date:

06/22/2017

Document Number:

666803284

### FIELD INSPECTION FORM

Loc ID 323981 Inspector Name: Murray, Richard On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10531  
 Name of Operator: VANGUARD OPERATING LLC  
 Address: 5847 SAN FELIPE #3000  
 City: HOUSTON State: TX Zip: 77057

**Findings:**

- 8 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S
Axelson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211402	WELL	PR	01/30/2005	GW	045-07162	GIBSON GULCH UNIT 14-30	PR

**General Comment:**

[2017 Flowline NTO Inspection 1000' Buffer](#)

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#	Comment	Corrective Action	Date	corrective date
Type: Flow Line	#				
		In use; 1-2" steel risers at wellhead, 2-2" risers at separators, 1-2" risers at tanks, 1-2", 1-3" risers at gas meter run,			
Type: Horizontal Heated Separator	# 1				
		39.492243/-107.599129			
Type: Gas Meter Run	# 1				
		39.492178/-107.599177			
Type: Plunger Lift	# 1				
		39.492270/-107.598918			

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		39.492174,-107.598954
Comment:	<input type="text"/>				
Corrective Action:	<input type="text"/>				Date: <input type="text"/>

**Paint**

Condition	Adequate	<input type="text"/>
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 211402 Type: WELL API Number: 045-07162 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Plunger lift](#)

Corrective Action:

Date:

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:  Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Seeding	Pass					
		Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666803285	NTO	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4177794">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4177794</a>
666803286	NTO 2	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4177795">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4177795</a>