

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/14/2017

Submitted Date:

06/16/2017

Document Number:

674603383**FIELD INSPECTION FORM**

Loc ID _____	Inspector Name: _____ Maclaren, Joe	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>4680</u> Name of Operator: <u>DCP MIDSTREAM LP</u> Address: <u>370 17TH STREET - SUITE 2500</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				Findings: <u>2</u> Number of Comments <u>0</u> Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Hayes, Branden	970-373-8905	bshayes@dcpmidstream.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
JONES, JEANETTE		jajones@dcpmidstream.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451003	SPILL OR RELEASE	AC	06/08/2017		-	Maggie 10"	EG

General Comment:

Engineering Integrity Inspection performed on June 14th, 2017 in response to initial form 19 spill report Doc #401303996 received by COGCC on 06/08/2017 that outlines: DCP Environmental was informed by DCP Pipeline group of a possible pipeline release on June 5th, 2017 around 10:00 am. At the time of notification the DCP pipeline group had identified that a 10 inch gathering line had developed a leak, but there was no visible staining on the surface to indicate soil contamination. The pipeline was shut-in and depressurized and will not return to operation until the leak has been repaired. The pipeline repair crew and excavation team are currently scheduled to repair the gathering line the week of June 12th, 2017. Details of observations made during this field inspection are available in the comment section of this report. Photo's uploaded and can be accessed via link(s) at the end of this report.

Inspected Facilities

Facility ID: 451003 Type: SPILL OR API Number: - Status: AC Insp. Status: EG

COGCC Comments

Comment	User	Date
<p>The area where the possible release occurred has been grubbed/ graded. It is unclear if pipeline repairs have already been completed. There were no DCP Midstream employees or contract personnel on site; no cleanup/ remediation or pipeline repair work taking place at the time of this field inspection.</p> <p>Note: Please document the findings of root cause of failure evaluation, measures taken to prevent the problem from reoccurring and description of pipeline repairs completed on the COGCC supplemental form 19.</p>	maclarej	06/16/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401310759	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4172524
674603385	Site of possible release - clean & grubbed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4172523