

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/14/2017

Submitted Date:

06/16/2017

Document Number:

674603384

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 4680
Name of Operator: DCP MIDSTREAM LP
Address: 370 17TH STREET - SUITE 2500
City: DENVER State: CO Zip: 80202

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
JONES, JEANETTE		jajones@dcpmidstream.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Hayes, Branden	970-373-8905	bshayes@dcpmidstream.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451002	SPILL OR RELEASE	AC	06/08/2017		-	Maggie 8"	EG

General Comment:

Engineering Integrity Inspection performed on June 14th, 2017 in response to initial form 19 spill report Doc #401303989 received by COGCC on 06/08/2017 that outlines: DCP Environmental was informed by DCP Pipeline group of a possible pipeline release on June 2nd, 2017 around 9:00 am. At the time of notification the DCP pipeline group had identified that a 8 inch gathering line had developed a leak, but there was no visible staining on the surface to indicate soil contamination. The pipeline was shut-in and depressurized and will not return to operation until the leak has been repaired. The pipeline repair crew and excavation team are currently scheduled to repair the gathering line the week of June 12th, 2017. Details of observations made during this field inspection are available in the comment section of this report.

Inspected FacilitiesFacility ID: 451002 Type: SPILL OR API Number: - Status: AC Insp. Status: EG**COGCC Comments**

Comment	User	Date
<p>There were no DCP Midstream employees or contract personnel on site; no cleanup/ remediation or pipeline repair work taking place at the time of this field inspection. It is unclear if pipeline repairs have already been completed.</p> <p>Note: Please document the findings of root cause of failure evaluation, measures taken to prevent the problem from reoccurring and description of pipeline repairs completed on the COGCC supplemental form 19.</p>	maclarej	06/16/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401310760	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4172525