

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/16/2017

Submitted Date:

06/19/2017

Document Number:

666803249**FIELD INSPECTION FORM**

Loc ID 335386 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Axelsson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276751	WELL	PR	04/02/2008	GW	045-10521	FERGUSON 34B-27-692	PR
276753	WELL	PR	10/10/2005	GW	045-10522	FERGUSON 44D-27-692	PR
276756	WELL	PR	06/01/2013	GW	045-10523	FERGUSON 44B-27-692	PR
276759	WELL	PR	04/02/2008	GW	045-10524	FERGUSON 34D-27-692	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Horizontal Heated Separator # 4

Comment: 39.492308/-107.648841

Corrective Action:

Date:

Type: Emission Control Device # 1

Comment: 39.492256/-107.648167

Corrective Action:

Date:

Type: Gas Meter Run # 0

Comment:

Corrective Action:

Date:

Type: Flow Line #

Comment: In use; 4-2" steel risers at wellhead, 14-2", 1-1" risers at separators, 3-1", 2-2" risers at tanks

Corrective Action:

Date:

Type: Plunger Lift # 4

Comment: 39.492215/-107.648766

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	3	200 BBLS	STEEL AST		39.492223,-107.648554	
Comment:						
Corrective Action:						Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	YES		
Comment:	Bradenhead valves open		
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 276751	Type: WELL	API Number: 045-10521	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:			Date:	
Facility ID: 276753	Type: WELL	API Number: 045-10522	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:			Date:	
Facility ID: 276756	Type: WELL	API Number: 045-10523	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:			Date:	
Facility ID: 276759	Type: WELL	API Number: 045-10524	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:			Date:	

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
		Culverts	Pass			
Gravel	Pass					
		Ditches	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401311846	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174000