

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/24/2017

Submitted Date:

06/19/2017

Document Number:

674901736

### FIELD INSPECTION FORM

Loc ID 334324 Inspector Name: Hughes, Jim On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 5  
 Name of Operator: COLORADO OIL & GAS CONSERVATION  
 Address: 1120 LINCOLN ST SUITE 801  
 City: DENVER State: CO Zip: 80203

**Findings:**

7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267696	WELL	AC	06/15/2015	OBW	067-08801	MONITOR WELL 35-7-8-1	EI
267858	WELL	AC	06/15/2015	OBW	067-08811	MONITOR WELL 35-7-8-2	EI

**General Comment:**

On May 24, 2017 COGCC SW EPS Jim Hughes and West Environmental Supervisor Alex Fischer conducted an environmental field inspection of the COGCC SFTC MW 35-7-8 #1 and #2. For the most recent field inspection report for this facility, please refer to document #674901177.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Signs mounted to protective steel cages surrounding well heads.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Sign mounted to skid mounted shack housing ancillary equipment.	Date:	
Corrective Action:			

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	4' x 4' x 4' expanded metal and angle iron protective cages.		
Corrective Action:		Date:	

**Equipment:**

Type: Ancillary equipment	# 1		corrective date
Comment:	In-Situ data logger.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry.		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 267696 Type: WELL API Number: 067-08801 Status: AC Insp. Status: EI

Facility ID: 267858 Type: WELL API Number: 067-08811 Status: AC Insp. Status: EI

### Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: 

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

### COGCC Comments

Comment	User	Date
<p>On May 24, 2017 COGCC SW EPS Jim Hughes and West Environmental Supervisor Alex Fischer conducted an environmental field inspection of the COGCC SFTC MW 35-7-8 #1 and #2. For the most recent field inspection report for this facility, please refer to document #674901177.</p> <p>During this site visit, all of the desiccant packs and the desi-tube were replaced. This was last performed on 6/24/16.</p>	hughesj	06/19/2017

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401312077	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174142">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174142</a>
674901737	SFTC MW #2 well head and protective cage.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174137">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174137</a>
674901739	Troll Link 201 equipment enclosure.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174138">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174138</a>