

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/06/2017

Submitted Date:

06/19/2017

Document Number:

674901746**FIELD INSPECTION FORM**Loc ID 322126 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46685Name of Operator: KINDER MORGAN CO2 CO LPAddress: 1001 LOUISIANA ST SUITE 1000City: HOUSTON State: TX Zip: 77002**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Swift, Barry	970-882-5545	barry_swift@kindermorgan.com	SW Inspection Reports
Millican, Chris	970-882-5504	chris_millican@kindermorgan.com	SW Inspection Reports
Conway, James	970-882-5505	james_conway@kindermorgan.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290489	WELL	PA	06/13/2011	STRT	033-06130	DOE CANYON 5	EI

General Comment:

On June 6, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Kinder Morgan Doe Canyon #5. Kinder Morgan representatives Mike Hannigan and Chris Millican were on site during this field inspection. Arcadis and Enviro-Drill Inc. employees were installing monitoring wells for REM project #9853.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	Location sign near locked gate at entrance to access road.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	290489	Type:	WELL	API Number:	033-06130	Status:	PA	Insp. Status:	EI

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action: Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On June 6, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Kinder Morgan Doe Canyon #5. Kinder Morgan representatives Mike Hannigan and Chris Millican were on site during this field inspection. Arcadis and Enviro-Drill Inc. employees were installing monitoring wells for REM project #9853. For the most recent field inspection report for this facility, please refer to document #200312277. During this field inspection, Kinder Morgan representative Mike Hannigan showed COGCC SW EPS the proposed locations of groundwater monitoring wells that Enviro-Drill Inc. and Arcadis were installing.	hughesj	06/19/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401313088	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174882
674901747	Enviro-Drill Inc. installing monitoring well.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174853
674901748	Installing groundwater monitoring wells.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174854
674901749	Arcadis and Enviro-Drill Inc. installing MW.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4174855