

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/08/2017

Submitted Date:

06/17/2017

Document Number:

687900028**FIELD INSPECTION FORM**

Loc ID 308829 Inspector Name: DURAN, JOHN On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: PO BOX 6501City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Trujillo, Irwin	719-846-0272/719-859-2264	irwin_trujillo@xtoenergy.com	Sr. Env. Tech., Raton Basin
Fitzgerald, Edie	719-845-2108/719-859-1394	Edie_Fitzgerald@xtoenergy.com	Env. Tech, Raton Basin
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Harrison, Lyndon	505-333-3100	Lyndon_Harrison@xtoenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282948	WELL	PR	11/02/2007	GW	071-08697	GOLDEN EAGLE 19-10	PR

General Comment:

2017 Flowline NTO Inspection
 Shadowing Operator Pressure Testing Team
 XTO Team : Joseph Garcia, Carl Vialpando, Joe Amato

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	(GMR,VS) shed, PCPump		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Flow Line	# 1		
Comment:	IN USE : 1 - 4" Casing line riser at wellhead (37.15779/-104.92484).		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	IN USE : 1 - 2" Fuel/Gas riser at separator (37.15765/-104.92484)		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	IN USE : 1 - 3" tubing line riser at wellhead (37.15779/-104.92484) to separator.		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	IN USE : 1 - 3" tubing line riser at separator (37.15776,-104.92484) to pit.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities

Facility ID: 282948 Type: WELL API Number: 071-08697 Status: PR Insp. Status: PR

Flowline

#1	Type: Well Site	1 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Well Site Size: 3" Material: Poly
 Variance: Yes Age: 5-10 Yrs Contents: Produced Water

Integrity Summary

Failures: Spills: No Repairs Made: No
 Coatings: Yes External H2S: No Cathodic Protection: No

Pressure Testing

Witnessed: Yes Test Result: Pass Charted: No

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Material : Carbon Steel riser to Poly line. No physical chart in the field, but XTO used a Crystal Digital Pressure Guage - AMETEK xpzi 5,000 psig (To record pressures). Time : 10:20 am, P=18.3 psig, Time : 10:35 am, P=18.3 psig. Joe Amato says at the end of day that Guage recorded the ramp up to 18.3 psig. They will do over.

Corrective Action:

Date:

#2	Type: Well Site	1 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Well Site Size: 3" Material: Poly
 Variance: Yes Age: 5-10 Yrs Contents: Produced Water

Integrity Summary

Failures: Spills: No Repairs Made: No
 Coatings: Yes External H2S: No Cathodic Protection: No

Pressure Testing

Witnessed: Yes Test Result: Pass Charted: Yes

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Material : Carbon Steel riser to Poly line. No physical chart in the field, but XTO used a Crystal Digital Pressure Guage - AMETEK xpzi 5,000 psig (To record pressures). Time : 11:05 am, P=9.8 psig, Time : 11:20 am, P=9.8 psig.

Corrective Action:

Date:

#3	Type: Well Site	1 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Well Site Size: 4" Material: Poly
 Variance: No Age: 5-10 Yrs Contents: Natural Gas

Integrity Summary

Failures: Spills: No Repairs Made: No
 Coatings: Yes External H2S: No Cathodic Protection: No

Pressure TestingWitnessed: YesTest Result: PassCharted: YesCOGCC Rules(check all that apply)☐ 1101. Installation and Reclamation☒ 1102. Operations, Maintenance, and Repair☐ 1103. AbandonmentComment:

Material : Carbon Steel riser to Poly line. No physical chart in the field, but XTO used a Crystal Digital Pressure Guage - AMETEK xpzi 5,000 psig (To record pressures). Time : 11:32 am, P=5.4 psig, Time : 11:47 am, P=5.5 psig.

Corrective Action:

Date:

#4 Type:Well Site

1 of Lines

Flowline DescriptionFlowline Type: Well SiteSize: 2"Material: PolyVariance: NoAge: 5-10 YrsContents: Natural GasIntegrity Summary

Failures:

Spills: NoRepairs Made: NoCoatings: Yes ExternalH2S: NoCathodic Protection: NoPressure TestingWitnessed: YesTest Result: PassCharted: YesCOGCC Rules(check all that apply)☐ 1101. Installation and Reclamation☒ 1102. Operations, Maintenance, and Repair☐ 1103. AbandonmentComment:

Material : Carbon Steel riser to Poly line. No physical chart in the field, but XTO used a Crystal Digital Pressure Guage - AMETEK xpzi 5,000 psig (To record pressures). Time : 12:14 pm, P=5.9 psig, Time : 12:29 pm, P=5.9 psig. The first attempt a leak was found at 1" bushing under guage, detected with soapy water. The 1 " bushing was replaced and with new tape the pressure held.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: c**Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: NO2+ feet Freeboard: YESComment: 30' x 70'Corrective Action: Date: Monitoring: Monitoring Type: Comment: Other:

Blue stake

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401311637	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4173848