



photo 1: Facing west toward the location. The native vegetation has fully re-established however, pipe risers remain at the location.



photo 2:



photo 3:



photo 4: