

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/21/2017

Submitted Date:

06/26/2017

Document Number:

674603409**FIELD INSPECTION FORM**Loc ID 308559 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10084Name of Operator: PIONEER NATURAL RESOURCES USA INCAddress: 5205 N O'CONNOR BLVD STE 200City: IRVING State: TX Zip: 75039**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	
ROYBAL, JAMES	719-845-4323	james.roybal@pxd.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273977	WELL	TA	07/28/2015	GW	071-08224	SAND PEBBLES 13-33	EG

**General Comment:**2017 Flowline NTO Inspection 1000' Buffer; Shadowing Operator Identifying/ Integrity Team using RMLD and FLIR Equipment

**Inspected Facilities**Facility ID: 273977 Type: WELL API Number: 071-08224 Status: TA Insp. Status: EG**Flowline**

#1	Type:	of Lines
----	-------	----------

Flowline Description

Flowline Type:	Size:	Material:
Variance:	Age:	Contents:

Integrity Summary

Failures:	Spills:	Repairs Made:
Coatings:	H2S:	Cathodic Protection:

Pressure Testing

Witnessed:	Test Result:	Charted:
------------	--------------	----------

COGCC Rules(check all that apply)☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: COGCC Inspector met with Pioneer Resources Operations Compliance Foreman Zachary Snow (along with other personnel) and witnessed Remote Methane Leak Detection (RMLD) instrumentation being used at this location. The flowlines and production equipment on site were surveyed for gas leaks; NO leaks were detected with the RMLD equipment.

Corrective Action:

Date: