

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/21/2017

Submitted Date:

06/22/2017

Document Number:

666803268

FIELD INSPECTION FORM

Loc ID 336022 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10447
 Name of Operator: URSA OPERATING COMPANY LLC
 Address: 1600 BROADWAY ST STE 2600
 City: DENVER State: CO Zip: 80202

Findings:

- 9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284504	WELL	PR	06/11/2013	GW	045-12189	HANGS B1	PR
284505	WELL	PR	06/11/2013	GW	045-12190	HANGS B3	PR

General Comment:

[2017 Flowline NTO Inspection 1000' Buffer](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	Area	Volume	corrective date
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	#		
Comment:	Not in use 4-2", 2-3", 1-1" Marked with paint, see photo		
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:	39.534245/-107.678684		
Corrective Action:			Date:
Type: Plunger Lift	# 2		
Comment:	39.534468/*-107.678240		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 4		
Comment:	39.534252/-107.677947		
Corrective Action:			Date:
Type: Flow Line	#		
Comment:	In use; 2-2" steel risers at wellhead, 8-2", 2-3", 1-1" risers at separators, 2-3", 1-1" risers at tanks, 1-1" gas feed to ECB		
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 284504 Type: WELL API Number: 045-12189 Status: PR Insp. Status: PR

Producing Well

Comment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID: 284505 Type: WELL API Number: 045-12190 Status: PR Insp. Status: PR

Producing Well

Comment: [Plunger lift](#)

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	In Process					
Gravel	Pass					

Comment: Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT
Attached Documents
 You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401316451	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4177808
666803278	URSA NTO 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4177785
666803280	URSA NTO	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4177786
666803281	URSA NTO 3	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4177787
666803282	URSA NTO 4	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4177788