

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/14/2017

Submitted Date:

06/14/2017

Document Number:

675103677

**FIELD INSPECTION FORM**

Loc ID 323968 Inspector Name: GRANAHAN, KYLE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100185  
Name of Operator: ENCANA OIL & GAS (USA) INC  
Address: 370 17TH ST STE 1700  
City: DENVER State: CO Zip: 80202-

**Findings:**

- 11 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
, Encana		cogcc.inspections@encana.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211375	WELL	PR	02/05/1997	GW	045-07135	BOULTON 33-15 (O33NE)	EG

**General Comment:**

[2017 Flowline NTO inspection 1000' buffer](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:	<a href="#">Present/complete</a>		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	<a href="#">Present/complete</a>		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	<a href="#">Present/complete</a>		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: [800-791-7691](#)

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	LOCATION		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Gas Meter Run	# 1		corrective date
Comment:	<a href="#">39.47955/-107.66837</a>		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	<a href="#">39.47951/-107.66829</a>		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		

Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	#		
Comment:	IN USE; 1-2" steel riser from well to separator. 1 – 2" steel riser from gas out separator to sales line. 1 – 1" water/oil dump line from separator to tank. 1 – 1" well blow down line from separator to tank. 1-1" water/oil dump line from separator to tank battery.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	<100 BBLS	STEEL AST		39.479620,-107.668330
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 211375 Type: WELL API Number: 045-07135 Status: PR Insp. Status: EG

**Producing Well**

Comment: PR - via plunger lift, no leaks/venting - bradenhead/well pressure remotely monitored.

Corrective Action:

Date:

**Flowline**

#1	Type: Well Site	of Lines
----	-----------------	----------

Flowline Description

Flowline Type: Well Site Size: Material:  
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:  
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation  1102. Operations, Maintenance, and Repair  1103. Abandonment

Comment: IN USE; 1-2" steel riser from well to separator. 1 - 2" steel riser from gas out separator to sales line. 1 - 1" water/oil dump line from separator to tank. 1 - 1" well blow down line from separator to tank. 1-1" water/oil dump line from separator to tank battery.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Compaction	Pass					
Gravel	Pass					
		Compaction	Pass			

Comment: [No sediment flow evident](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401316667	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4178139">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4178139</a>
675103678	Flowline photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4178136">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4178136</a>