

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/20/2017

Submitted Date:

06/21/2017

Document Number:

687900061

**FIELD INSPECTION FORM**

Loc ID 334205 Inspector Name: DURAN, JOHN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10084  
Name of Operator: PIONEER NATURAL RESOURCES USA INC  
Address: 5205 N O'CONNOR BLVD STE 200  
City: IRVING State: TX Zip: 75039

**Findings:**

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
294682	WELL	PR	06/12/2008	GW	071-09498	MAZATLAN 23-25	PR

**General Comment:**

2017 Flowline NTO Inspection  
Shadowing Operator Pressure Testing Team  
Pioneer Team : Zeke Sanchez, Vince Santisteven, Vince Santisteven Jr. and John Gonzales

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Type: Flow Line	# 1		
Comment:	NOT IN USE : 1 - 1" carbon steel riser for Mazatlan 23-25 and Mazatlan 23-25TR at separator (37.22726/-104.94881). Separator dump to pit. Marked and Locked out/Tagged out.		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	IN USE : 1 - 2" carbon steel Fuel/Gas riser at separator (37.22726/-104.94878).		
Corrective Action:		Date:	

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 294682 Type: WELL API Number: 071-09498 Status: PR Insp. Status: PR

**Flowline**

#1	Type: Well Site	1 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Well Site Size: 2" Material: Carbon Steel  
 Variance: No Age: 5-10 Yrs Contents: Natural Gas

Integrity Summary

Failures: Spills: No Repairs Made: No  
 Coatings: Yes External H2S: No Cathodic Protection: No

Pressure Testing

Witnessed: Yes Test Result: Pass Charted: Yes

COGCC Rules(check all that apply)

1101. Installation and Reclamation  1102. Operations, Maintenance, and Repair  1103. Abandonment

Comment: No physical chart in the field, but Pioneer used a Manifold Pressure Transducer : GP:50, Model #311ZCPZ2FNDR4, Serial # 183317, Pressure Range : 0 - 100 psig (Records pressure in the field). Manifold also has liquid guage : 0 - 100 psig. Time : 9:53 am, P=27 psig, Time : 10:08 am, P=26 psig.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401315406	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4176920">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4176920</a>