

June 28, 2017 COGCC Inspection of TEP Rocky Mountain LLC (TEP) Facility ID: 451109



Dozer and coring rig.



Overburden material being pushed with dozer.



Overburden material being pushed with dozer.



Overburden material being pushed with dozers.



Pipe and fractured rock.



Trench, sandbags, pipe, fractured rock.