

Inspection Photos

6/23/2017

Operator: ALLISON DRILLING COMPANY INC -
1350

Location ID: 402112

Inspection Doc. Number: 682502322

Washington County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: ALLISON DRILLING COMPANY INC -
1350
Location ID: 402112



Photo 1: Photo taken from the west end of the well location, facing east. Photo shows a black, hard material staining the soil throughout the well location, pits and access road.



Photo 2: Photo taken from the west end of the well location, facing west. Photo shows a black, hard material staining the soil throughout the well location, pits and access road.

Inspection Photos
Operator: ALLISON DRILLING COMPANY INC -
1350
Location ID: 402112



Photo 3: Photo taken from the north east end of the location, facing east. Photo shows pipe riser on location. Photo also shows a black, hard material staining the soil throughout the well location, pits and access road.



Photo 4: Photo taken from the north east end of the location, facing south. Photo shows pipe riser on location.

Inspection Photos
Operator: ALLISON DRILLING COMPANY INC -
1350
Location ID: 402112



Photo 5: Photo of pipe debris found at the pit.



Photo 6: Photo taken from the northeast corner of the southern pit, facing south. Photo shows a black, hard material staining the soil throughout the well location, pits and access road.

Inspection Photos
Operator: ALLISON DRILLING COMPANY INC -
1350
Location ID: 402112



Photo 7: Photo taken from the southwest corner of the southern pit, facing northeast. Photo shows a black, hard material staining the soil throughout the well location, pits and access road.



Photo 8: Photo taken from the southwest corner of the southern pit, facing east. Photo shows a black, hard material staining the soil throughout the well location, pits and access road.

Inspection Photos
Operator: ALLISON DRILLING COMPANY INC -
1350
Location ID: 402112



Photo 9: Photo taken from the northeast corner of the southern pit, facing west. Photo shows a black, hard material staining the soil throughout the well location, pits and access road.



Photo 10: Photo taken from the access road on the west end of the location. Photo taken from the northeast corner of the southern pit, facing south. Photo shows a black, hard material staining the soil on the access road.

Inspection Photos
Operator: ALLISON DRILLING COMPANY INC - 1350
Location ID: 402112



Photo 11: Photo taken from the access road on the west end of the location. Photo taken from the northeast corner of the southern pit, facing south. Photo shows a black, hard material staining the soil on the access road.