

Inspection Photos
Location Name: Kuipers 1
API: 05-057-06090



Photo 1. Overview of location taken at entrance facing north.



Photo 2. In Use riser at tank.

Inspection Photos
Location Name: Kuipers 1
API: 05-057-06090



Photo 3. Not in use flowline.



Photo 4. Oily waste.

Inspection Photos
Location Name: Kuipers 1
API: 05-057-06090



Photo 5. In use and not in use risers at wellhead.



Photo 6. Tank label missing capacity.