

Inspection Photos
Location Name: Dowdell 1
API: 05-057-06252



Photo 1. Insulated tank, no berm or labels.



Photo 2. Risers at tank not in use, not locked out tagged out.

Inspection Photos
Location Name: Dowdell 1
API: 05-057-06252



Photo 3. Steel riser not in use, not locked out tagged out.



Photo 4. Steel riser going into northern pit.

Inspection Photos
Location Name: Dowdell 1
API: 05-057-06252



Photo 5. Steel riser not in use, not locked out tagged out in southern pit.



Photo 6. Steel risers at separators locked out tagged out.

Inspection Photos
Location Name: Dowdell 1
API: 05-057-06252



Photo 7. Steel riser not in use, not locked out tagged out in southern pit.



Photo 8. Steel risers not in use at separator not locked out tagged out.

Inspection Photos
Location Name: Dowdell 1
API: 05-057-06252



Photo 9. Tank battery.



Photo 10. Steel risers not in use at wellhead not locked out tagged out.