

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/08/2017

Submitted Date:

06/29/2017

Document Number:

673404741

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100264
Name of Operator: XTO ENERGY INC
Address: PO BOX 6501
City: ENGLEWOOD State: CO Zip: 80155

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Bennet, Waylon		Waylon_Bennett@xtoenergy.com	XTO Integrity NTO contact
Dooling, Jessica	(970) 878-6800	Jessica_Dooling@xtoenergy.com	Piceance Basin Field

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451016	GAS GATHERING SYSTEM	AC	06/09/2017		-	6-inch gathering, Ryan's Gulch	EG

General Comment:

[2017 Flowline NTO Inspection Statewide](#)

Inspected Facilities

Facility ID: 451016 Type: GAS API Number: - Status: AC Insp. Status: EG

Flowline

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline Description

Flowline Type: Non-Well Site Size: 6" Material: Carbon Steel
 Variance: No Age: _____ Contents: Condensate

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: Yes Test Result: _____ Charted: Yes

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Line was isolated at 39.93573, -108.29642 and 39.89219, -108.29172. Gauge for test was placed at 39.91655, -108.30862. Gauge reading 130 psi when arrived on location. Pressure was bled off and stabilized at 119.5 psi, it held for 15 minutes and then line was bled off to 55.8 psi.

Corrective Action: _____

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673404753	Pressure testing photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4186553