

Inspected Facilities

Facility ID: 451019 Type: GAS API Number: - Status: AC Insp. Status: EG

Flowline

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline Description

Flowline Type: Non-Well Site Size: 4" Material: Carbon Steel
 Variance: No Age: _____ Contents: Condensate

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: Yes Test Result: _____ Charted: Yes

COGCC Rules (check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Line isolated at 39.86881, -108.28773 and 39.88703, -108.29462. Gauge at second coordinates. Line at 1 psi on arrival. Pressured up to 69.1 psi. At 5 minutes 69.1, at 10 minutes 67.3, at 15 minutes 66.8. Line contains flash condensate.

Corrective Action: _____

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673404755	Pressure test photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4186554