

# Flowline and Final Reclamation Inspection

June 29, 2017

Operator: PDC ENERGY INC - 69175

API: 05-123-11129

Weld County, CO

SESE Section 7 T6N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

**Inspection Photos**  
**Location Name: FRYE-SWANSON-FRYE #1**  
**API: 05-123-11129**



**Photo 1.** Photo taken from the northeast location, facing North. Appears stormwater and/or irrigation water run-on is flowing onto location which then travels across the eastern location through the wells. Gully erosion is occurring along the eastern location and off location.



**Photo 2.** Photo taken from the eastern location, facing North. Gully erosion evident from stormwater and/or irrigation water run-on onto location.

Inspection Photos  
Location Name: FRYE-SWANSON-FRYE #1  
API: 05-123-11129



**Photo 3.** Photo taken from the southern location, facing East. Gully erosion is occurring adjacent to the location from stormwater and/or irrigation water run-on onto location.



**Photo 4.** Photo taken from the area that would likely be the inlet of the culvert, facing East. Appears sediment has accumulated overtime blocking the inlet of a culvert-see following photo.



Inspection Photos  
Location Name: FRYE-SWANSON-FRYE #1  
API: 05-123-11129



**Photo 5.** Photo taken from the outlet of the culvert along a portion of the access road, facing Northeast. Did not observe the inlet of the culvert due to sediment build up overtime. Red arrows indicate the likely direction of current water flow.