

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/23/2017

Submitted Date:

06/29/2017

Document Number:

673715647**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 320681      Sherman, Susan      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10454Name of Operator: PETROSHARE CORPORATIONAddress: 9635 MAROON CIRCLE #400City: ENGLEWOOD      State: CO      Zip: 80112**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Powell, Harold	(918)-774-3120	hpowell@petrosharecorp.com	Field Op Manager
Lloyd, Bill	(720) 935-8256	blloyd@petrosharecorp.com	Operations Manager

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204446	WELL	PR	12/01/1994	OW	005-06531	BRUCHEZ-UPRR 1	EG

**General Comment:**2017 Flowline NTO Inspection 1000' Buffer

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: 303-500-1160

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

## Inspected Facilities

Facility ID: 204446 Type: WELL API Number: 005-06531 Status: PR Insp. Status: EG

## Producing Well

Comment: PR. Dec 2016 last reported to COGCC database. Contact COGCC Production.

Corrective Action:

Date:

## Flowline

#1 Type: Well Site

of Lines

## Flowline Description

Flowline Type: Well Site

Size: 2"

Material: Carbon Steel

Variance:

Age:

Contents:

## Integrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

## Pressure Testing

Witnessed: Yes

Test Result: Pass

Charted: Yes

## COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation

☒ 1102. Operations, Maintenance, and Repair

☐ 1103. Abandonment

Comment: Flowline test from well to treater. 0 psi prior to test.

0 min 18.1 psi  
5 min 18.3 psi  
10 min 17.7 psi  
15 min 17.2 psi  
0 psi after test  
Digital gauge used.

Corrective Action:

Date:

#2 Type: Sales Line

of Lines

## Flowline Description

Flowline Type: Sales Line

Size: 2"

Material: Carbon Steel

Variance:

Age:

Contents:

## Integrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

## Pressure Testing

Witnessed: Yes

Test Result: Pass

Charted: Yes

## COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation

☒ 1102. Operations, Maintenance, and Repair

☐ 1103. Abandonment

Comment: Flowline test from treater to GMR. 0 psi prior to test.

0 min 23.2 psi  
5 min 22.7 psi  
10 min 22.3 psi  
15 min 21.9 psi  
0 psi after test  
Digital gauge used.

Corrective Action:		Date:	
#3	Type: Dump Line	of Lines	
<b>Flowline Description</b>			
Flowline Type: <u>Dump Line</u>		Size: <u>2"</u>	Material: <u>Carbon Steel</u>
Variance:		Age:	Contents:
<b>Integrity Summary</b>			
Failures:		Spills:	Repairs Made:
Coatings:		H2S:	Cathodic Protection:
<b>Pressure Testing</b>			
Witnessed: <u>Yes</u>		Test Result: <u>Pass</u>	Charted: <u>Yes</u>
<b>COGCC Rules(check all that apply)</b>			
<input type="checkbox"/> 1101. Installation and Reclamation		<input checked="" type="checkbox"/> 1102. Operations, Maintenance, and Repair	<input type="checkbox"/> 1103. Abandonment
Comment:	Flowline test from treater to hot oil line. 0 psi prior to test. 0 min 20.2 psi 5 min 19.9 psi 10 min 19.8 psi 15 min 19.7 psi 0 psi after test Digital gauge used.		
Corrective Action:			Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673715675	Petroshare Corporation Bruchez-UPRR 1 EI	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4186800">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4186800</a>