

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/23/2017

Submitted Date:

06/26/2017

Document Number:

666803294**FIELD INSPECTION FORM**

Loc ID 336017 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 1600 BROADWAY ST STE 2600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**15 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282544	WELL	PR	09/21/2012	GW	045-11777	NORTH BANK E1	PR
292121	WELL	PR	01/24/2008	GW	045-14603	NORTH BANK E5	PR
292127	WELL	PR	01/25/2008	GW	045-14602	NORTH BANK E3	PR
295745	WELL	PR	04/06/2010	GW	045-15809	NORTH BANK E12	PR

**General Comment:**[2017 Flowline NTO Inspection 1000' Buffer](#)

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Flow Line

#

Comment: Not in use 4-2", 2-3/8" Marked with paint, see photo

Corrective Action:

Date:

Type: Flow Line

#

Comment: In use; 4-2" steel risers at wellhead, 12-2", 2-3", 1-1" risers at separators, 3-3" risers at tanks, 6-3", 1-1" gas feed to ECB

Corrective Action:

Date:

Type: Pig Station

# 1

Comment: 39.541687/-107.733371

Corrective Action:

Date:

Type: Ancillary equipment

# 2

Comment: Chemical units at wellhead

Corrective Action:

Date:

Type: Emission Control Device

# 1

Comment: 39.541634/-107.732904

Corrective Action:

Date:

Type: Plunger Lift

# 4

Comment: 39.541322/-107.733425

Corrective Action:

Date:

Type: Horizontal Heated Separator

# 4

Comment: 39.541375/-107.733138

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment: Centralized battery					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		39.541712,-107.732735
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		

Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	282544	Type:	WELL	API Number:	045-11777	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	292121	Type:	WELL	API Number:	045-14603	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	292127	Type:	WELL	API Number:	045-14602	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	295745	Type:	WELL	API Number:	045-15809	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB):  YES

Comment:

Pilot:  ON Wildlife Protection Devices (fired vessels):  YES

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Culverts	Pass			
Seeding	In Process					
Berms	Pass					
		Ditches	Pass			
		Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401319514	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4181010">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4181010</a>
666803295	NTO 2	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4181004">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4181004</a>
666803296	NTO 1	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4181005">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4181005</a>
666803297	NTO	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4181006">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4181006</a>