

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/26/2017

Submitted Date:

06/26/2017

Document Number:

666803298

### FIELD INSPECTION FORM

Loc ID 336013 Inspector Name: Murray, Richard On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10447  
 Name of Operator: URSA OPERATING COMPANY LLC  
 Address: 1600 BROADWAY ST STE 2600  
 City: DENVER State: CO Zip: 80202

**Findings:**

15 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278646	WELL	PR	02/01/2008	GW	045-10902	NORTH BANK C8	PR
278648	WELL	PR	01/19/2009	GW	045-10904	NORTH BANK C1	PR
278650	WELL	PR	10/15/2007	GW	045-10906	NORTH BANK C4	PR
288850	WELL	PR	01/01/2015	GW	045-13614	NORTH BANK C10	PR
288851	WELL	PR	06/13/2011	GW	045-13615	NORTH BANK C11	PR
288854	WELL	PR	01/25/2008	GW	045-13618	NORTH BANK C7	PR
288855	WELL	PR	03/30/2012	GW	045-13619	NORTH BANK C6	PR

**General Comment:**

[2017 Flowline NTO Inspection 1000' Buffer](#)

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

corrective date

Type: Horizontal Heated Separator # 8

Comment: [39.539586/-107.726789](#)

Corrective Action:

Date:

Type: Gas Meter Run # 1

Comment: [39.539834/-107.727490](#)

Corrective Action:

Date:

Type: Flow Line #

Comment: [In use; 7-2" steel risers at wellhead, 28-2", 4-3", risers at separators, 2-3" risers at tanks, 1-1", 1-3" gas feed to ECB](#)

Corrective Action:

Date:

Type: Flow Line #

Comment: [Not in use 1-1", 1-3", not Marked with paint, see photo](#)

Corrective Action:

Date:

Type: Plunger Lift # 7

Comment: [39.539505/-107.726943](#)

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLS	STEEL AST		39.539804,-107.727237

Comment:

Corrective Action:

Date:

**Paint**

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	300 BBLs	STEEL AST		
Comment:	Centralized battery				
Corrective Action:					Date:
<b>Paint</b>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	278646	Type:	WELL	API Number:	045-10902	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	278648	Type:	WELL	API Number:	045-10904	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	278650	Type:	WELL	API Number:	045-10906	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	288850	Type:	WELL	API Number:	045-13614	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	288851	Type:	WELL	API Number:	045-13615	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	288854	Type:	WELL	API Number:	045-13618	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	288855	Type:	WELL	API Number:	045-13619	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:  Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Seeding	In Process					
		Gravel	Pass			
		Ditches	Pass			
		Culverts	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401319516	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4181011">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4181011</a>
666803299	NTO	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4181007">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4181007</a>
666803300	NTO 1	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4181008">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4181008</a>
666803301	NTO 2	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4181009">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4181009</a>