

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/29/2017

Submitted Date:

07/03/2017

Document Number:

681700604**FIELD INSPECTION FORM**

Loc ID 318467 Inspector Name: Arauza, Steven On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 46290Name of Operator: K P KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Lara-Mesa, Susana		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241346	WELL	PR	04/12/1977	OW	123-09135	AMOCO-CHARTER SCHNEIDER 12	EI

General Comment:

COGCC Environmental inspection of wellhead and pump jack. Well was incapable of production on inspection date: the pump jack belt had been removed; the belt cover was sitting on the side of the pump jack; and power had been shut off to the pumping unit.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Operator information on pumpjack sign is faded.		
Corrective Action:	Repair or replace sign to comply with Rule 210.b	Date:	09/03/2017

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Pump jack belt cover is sitting on SW corner of pump jack.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	08/03/2017

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Propane tank plumbed to wellhead has secondary containment device.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 241346 Type: WELL API Number: 123-09135 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
681700612	Well sign with faded operator info.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4188949
681700613	Pump jack belt cover.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4188950
681700614	Inactive wellhead with propane tank.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4188951
681700615	Propane tank with secondary containment.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4188952