

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/26/2017

Submitted Date:

06/30/2017

Document Number:

673404744**FIELD INSPECTION FORM**
 Loc ID _____ Inspector Name: Waldron, Emily On-Site Inspection ☐
 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: PO BOX 6501City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Dooling, Jessica	(970) 878-6800	Jessica_Dooling@xtoenergy.com	Piceance Basin Field
Bennet, Waylon		Waylon_Bennett@xtoenergy.com	XTO Integrity NTO contact

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451233	GAS GATHERING SYSTEM	AC	06/27/2017		-	16-inch gas gathering line	EG

General Comment:

[2017 Flowline NTO Inspection 1000' Buffer](#)
[Shadowing Operator Pressure Testing Team](#)

Inspected FacilitiesFacility ID: 451233 Type: GAS API Number: - Status: AC Insp. Status: EG**Flowline**

#1	Type: Non-Well Site	of Lines	
----	---------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: 16" Material: Carbon Steel
 Variance: Age: Contents: Natural Gas

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Yes Test Result: Charted: Yes

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Line isolated at 39.89212, -108.25010 and 39.89932, -108.29287. Gauge placed at 39.89537, -108.25407. Gauge read 109psi and pressured up to 129.4 psi. at 5 min 129.1 psi, at 10 min 129.1 psi, at 15 min 129.1 psi. Bled off to 105.7 psi.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673404761	Pressure test photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4189330